

REPORT OF CHANNEL CONDITIONS

100 TO 400 FEET WIDE

To: Navigation Interests			From: U.S. Army Corps of Engineers - Charleston 69A Hagood Avenue Charleston, SC 29403				
RIVER/HARBOR NAME AND STATE LITTLE RIVER INLET SOUTH CAROLINA					MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Tangent 1 10+00 to 47+30	02-04-2021	300	0.70	12.0	10	9	8
Tangent 2 47+30 to 71+45	02-04-2021	300	0.40	12.0	0	0	0
Tangent 3 71+45 to 106+28	02-04-2021	300 90	0.60	12.0	4	2	2
Tangent 4 106+28 to 151+32	02-04-2021	90	0.90	12.0	11	10	14
Tangent 5 151+32 to 161+07	02-04-2021	90	0.30	12.0	12	5	18
<p>1. All depths refer to local mean lower low water (MLLW) 2. The information shown represents the results of surveys made on the dates indicated and reflects the general conditions at that time 3. The right and left sides of the channel refer to travel in the general direction when entering from seaward 4. Tangent one dead ends into a shoal. Tangent two is impassable due to shoaling. Follow USCG NAVAIDS through this area.</p>							