



REPORT OF CHANNEL CONDITIONS  
100 TO 400 FEET WIDE

To: Navigation Interests		From: U.S. Army Corps of Engineers - Charleston 69A Hagood Avenue Charleston, SC 29403					
RIVER/HARBOR NAME AND STATE GEORGETOWN HARBOR SOUTH CAROLINA					MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Range D 354+91 to 443+10	03-15-2016	400	1.70	27.0	26.3	26.8	26.4
Range E 443+10 to 741+44	03-15-2016	400 780	5.70	27.0	18.8	19.1	18.3
Frazier Bend 741+44 to 778+90	03-15-2016	400 780	0.70	27.0	22.9	23.3	22.2
Rabbit Island Channel 7789+0 to 895+05	03-15-2016	400 740	2.20	27.0	25.4	24.7	24.1
Sampit Channel (A) 895+05 to 964+72	03-15-2016	250 740	1.30	27.0	3.9	0.9	0.6
Bypass Channel (B,C) 0+00 to 55+70	03-15-2016	100 300	1.20	12.0	8.6	6.4	8.9
<p>1. All depths refer to local mean lower low water (MLLW)                  2. The information shown represents the results of surveys made on the dates indicated and reflects the general conditions at that time                  3. The right and left sides of the channel refer to travel in the general direction when entering from seaward                  4. Only minimum depths based on survey lines listed                  A. Maintained 300' wide                  B. Maintained 100' wide                  C. Maintained 12' depth</p>							