

**REPORT OF CHANNEL CONDITIONS  
400 FEET WIDE OR GREATER**

To: Navigation Interests		From: U.S. Army Corps of Engineers - Charleston 69A Hagood Avenue Charleston, SC 29403						
RIVER/HARBOR NAME AND STATE GEORGETOWN HARBOR SOUTH CAROLINA					MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD			
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Entrance Channel 0+00 to 144+70	06-18-2019	600	2.70	27	21.9	19.9	16.2	14.7
Range B 144+70 to 196+47	06-18-2019	600	1.00	27	22.2	24.4	26.8	19.0
South Island Bend Tang. 1 196+47 to 233+53	06-18-2019	600	0.70	27	27.4	17.9	12.3	8.8
South Island Bend Tang. 2 233+53 to 262+26	06-18-2019	600	0.50	27	30.5	29.8	23.2	17.1
Range C 262+26 to 354+91	06-18-2019	600	1.80	27	19.6	20.3	20.6	24.6
Range D 354+91 to 443+10	06-18-2019	400	1.70	27	24.5	24.9	27.3	25.1
Range E 443+10 to 741+44	06-18-2019	400 780	5.70	27	15.9	16.7	16.8	15.4
Frazier Bend 741+44 to 778+90	06-18-2019	400 780	0.70	27	23.3	23.9	23.5	22.5
Rabbit Island Channel 7789+0 to 895+05	06-18-2019	400 740	2.20	27	24.2	25.5	26.1	22.8
Sampit Channel 895+05 to 964+72	06-18-2019	250 740	1.30	27	1.5	0.7	0.7	0.3
Steel Mill Channel 964+72 to 982+69	06-18-2019	300 610	0.30	27	3.9	0.8	0.7	0.4
PaperMill Channel 0+00 to 12+70	06-18-2019	400 780	0.20	27	14.4	19.3	19.8	20.6
PaperMill Turning Basin 12+70 to 25+37	06-18-2019	400 800	0.20	27	3.8	16.3	16.9	9.3
Bypass Channel 0+00 to 55+70	06-18-2019	100 300	1.20	12	4.6	6.5	7.7	6.8
1. All depths refer to local mean lower low water (MLLW) 2. The information shown represents the results of surveys made on the dates indicated and reflects the conditions at that time 3. The right and left sides of the channel refer to travel in the general direction when entering from seaward 4. Minimum depths based on survey lines shown								