

REPORT OF CHANNEL CONDITIONS
400 FEET WIDE OR GREATER

To: Navigation Interests		From: U.S. Army Corps of Engineers - Charleston 69A Hagood Avenue Charleston, SC 29403						
RIVER/HARBOR NAME AND STATE GEORGETOWN HARBOR SOUTH CAROLINA					MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD			
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Entrance Channel 0+00 to 144+70	09-15-2021	600	2.70	27	19.0	16.4	15.9	15.7
Range B 144+70 to 196+47	09-15-2021	600	1.00	27	21.2	25.3	27.7	21.6
South Island Bend Tang. 1 196+47 to 233+53	09-15-2021	600	0.70	27	28.0	19.3	8.3	6.6
South Island Bend Tang. 2 233+53 to 262+26	09-15-2021	600	0.50	27	31.1	28.5	23.9	19.0
Range C 262+26 to 354+91	09-15-2021	600	1.80	27	18.6	21.5	20.1	23.2
Range D 354+91 to 443+10	09-15-2021	400	1.70	27	24.4	26.2	25.0	24.7
Range E 443+10 to 741+44	09-15-2021	400 780	5.70	27	14.8	16.7	17.0	15.8
Frazier Bend 741+44 to 778+90	09-15-2021	400 780	0.70	27	23.2	23.4	23.4	21.7
Rabbit Island Channel 7789+0 to 895+05	09-15-2021	400 740	2.20	27	24.9	26.6	25.8	21.6
Sampit Channel 895+05 to 964+72	09-15-2021	250 740	1.30	27	1.3	0.6	0.5	0.2
Steel Mill Channel 964+72 to 982+69	09-15-2021	300 610	0.30	27	2.5	0.7	0.6	0.4
PaperMill Channel 0+00 to 12+70	09-15-2021	400 780	0.20	27	14.5	20.1	20.0	21.4
PaperMill Turning Basin 12+70 to 25+37	09-15-2021	400 800	0.20	27	12.5	17.1	15.6	8.2
Bypass Channel 0+00 to 55+70	09-15-2021	100 300	1.20	12	4.4	6.5	7.9	7.0