REPORT OF CHANNEL CONDITIONS 400 FEET WIDE OR GREATER

DATE OF SURVEY 03-16-2022 03-16-2022	AUTHO WIDTH (feet) 1241	good Ave ston, SC 2 DRIZED PRE LENGTH (miles)	29403	WIDTH LEFT OUTSIDE	UM DEPT I OF CHAI FROM SE LEFT INSIDE	NNEL ENT AWARD RIGHT INSIDE	
SURVEY 03-16-2022	AUTHO WIDTH (feet) 1241	DRIZED PRO	OJECT DEPTH	WIDTH LEFT OUTSIDE	I OF CHAN FROM SE LEFT INSIDE	NNEL ENT AWARD RIGHT INSIDE	RIGHT
SURVEY 03-16-2022	WIDTH (feet) 1241	LENGTH	DEPTH	WIDTH LEFT OUTSIDE	I OF CHAN FROM SE LEFT INSIDE	NNEL ENT AWARD RIGHT INSIDE	RIGHT
SURVEY 03-16-2022	WIDTH (feet) 1241	LENGTH	DEPTH	LEFT OUTSIDE	FROM SE LEFT INSIDE	AWARD RIGHT INSIDE	RIGHT
SURVEY 03-16-2022	WIDTH (feet) 1241	LENGTH	DEPTH	OUTSIDE	LEFT INSIDE	RIGHT INSIDE	
SURVEY 03-16-2022	WIDTH (feet) 1241	LENGTH	DEPTH	OUTSIDE	INSIDE	INSIDE	
SURVEY 03-16-2022	(feet) 1241						OUTSIDE
03-16-2022	(feet) 1241	(miles)			QUARTER		
			((feet)	(feet)	(feet)	(feet)
	300						
03-16-2022		0.70	45	27.7	31.6	28.6	24.6
03-16-2022							
	999	0.20	45	32.9	33.5	34.4	34.9
				No			
03-16-2022	200	0.60	30	Data	20.0	22.9	20.2
1			1				<u>µ</u>
					No	No	No

1. All depths refer to local mean lower low water (MLLW)

2. The information shown represents the results of surveys made on the dates indicated and reflects the general conditions at that time

3. The right and left sides of the channel refer to travel in the general direction when entering from seaward