REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE

Date 1/08/2019

To: Navigation Interests	From:	U.S. Army Corps of Engineers - Charleston 69A Hagood Avenue Charleston, SC 29403					
RIVER/HARBOR NAME AND STATE LITTLE RIVER INLET SOUTH CAROLINA					MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Tangent 1 10+00 to 47+30	01-08-2019	300	0.70	12.0	7	2	3
Tangent 2 47+30 to 71+45	01-08-2019	300	0.40	12.0	1	1	1
Tangent 3 71+45 to 106+28	01-08-2019	300 90	0.60	12.0	5	3	3
Tangent 4 106+28 to 151+32	01-08-2019	90	0.90	12.0	9	10	11
Tangent 5 151+32 to 161+07	01-08-2019	90	0.30	12.0	No Data	13	22

1. All depths refer to local mean lower low water (MLLW)
2. The information shown represents the results of surveys made on the dates indicated and reflects the general conditions at that time
3. The right and left sides of the channel refer to travel in the general direction when entering from seaward